
MATHE DEARMAN



The Stainless Steel Pit Depth Gauge mounts on the end of the Q.C. Welder's Gauge housing. It can be used to measure pit-depth, weld-height, and "Hi-Lo" in English or Metric Measurement. The Pit Depth Gauge is sold separately from Quality Control (Q.C.) Welders Gauge.

EMATHE E

Q.C. WELDER'S GAUGE

The Mathey Dearman's Q.C. Welder's Gauge measures inside "Hi-Lo" and welding gap. This tool helps the user to avoid Q.C. rejections. Read directions inside.


Also Available:

Pit-Depth Gauge (Cat No. D254)

The Pit-Depth Gauge mounts on the end of the O.C. Welder's Gauge housing. It can be used to measure pit-depth, weld height, and "Hi-Lo". This product is not included and is sold separately.



Measuring Weld Height



Measuring Pit Depth



Measuring Outside Hi-Lo

Mathey Dearman, Inc. 4344 S. Maybelle Ave. Tulsa, OK USA 74107 (918) 447-1288 Fax: (918) 447-0188 Email: sales@mathey.com www.mathey.com

C.I.A. Mathey Italiana, s.r.l. Via Isonzo, 26 20050 San Damiano di Brugherio (Mi) Italy (39) (039) 831019-2020021 Fax: (39) (039) 2020079 Email: ciamathey@promo.it www.ciamathey.com



Cat No. D253E (English) or Cat No. D253M (Metric)

